Fault Location Based 9


Fault Location Based on

Topography



utah: Am. Assoc. F v. 39, p. 385-481. Utahi Walton, P.T., 1955, Wasatch riuccus. M Assoc. Petroleum Geologists Bull., 1955 Fields

Reproduced in Doelling's Report (1972)



Fault Distance from Section 15 East Side

9 Mine Workings

Doelling, H.H., 1972, Central Utah Coal Fields: Sevier-Sanpete, Wasatch Plateau, Book Cliffs and Emery, Utah Geological and Mineralogical Survey, Monograph Series No. 3., p. 190-191. 1972

USDA Forest Service, Region 4, Manti-La Sal National Forest, Ferron-Price Ranger District, 1997, Environmental Assessment, Lease-By-Application No. Figure 2, Mill Fork Lease Tract

1

1997

Manti-


Proposed Action, p. I-4.

I, KENNETH S. FLECK, LICENSED PROFESSIONAL GEOLOGIST IN THE STATE OF UTAH, HEREBY CERTIFY THAT THE INFORMATION DEPICTED IN THIS DRAWING IS TRUE AND ACCURATE TO THE BEST OF MY


KNOWLEDGE AND BELIEF

Fault Location Based

8



Fault Location Based



2001

C/015/018, Energy West Mining Co., 2001, Deer Creek Mine Mill Fork Lease ML-48528 Permit No. Geologic Formations Map Section R645-301-600 Geology, MFU1823D

Andalex Mining Co., 1997 – Mine Mine Workings Map

1997


1

2002

,2002

Genwal


Fault Location Based on Topography



2005

From Energy West Underground Drilling Application

Fault Location Based on Topography and Aerial Photography Interpretation



Various Publications and Interpretations Joes Valley Fault Locations in Section 15 1955 - Present

Scale 5000'

CAD FILE NAME/DISK#: FIGURE GF-2

HUNTINGTON, UTAH 84528	MINING COMPANY	ENERGY
		WEST

Deer Creek Mine — Mill Fork Joes Valley Fault Locations Sec. 15, T.16 S. R.6 E. Mill Fork

)RAWN BY: K.S. FLECK AS SHOWNFIGURE GF-

March 1, 2006 | SHEET _1_ OF _1_

REV.